



Department of Water

320 W. Monument Avenue
Dayton, Ohio 45402
(937) 333-3725 | Fax (937) 333-6768
www.daytonohio.gov

TO: Proposers on RFP No. 21-012WTWT

FROM: City of Dayton, Ohio
Department of Aviation
Department of Water, Division of Water Reclamation

SUBJECT: ADDENDUM NO.1 - Questions and Answers

The City of Dayton received questions relating to our RFP No. 21-012WTWT.

The following are the questions with answers for this RFP. Please consider this document in preparation of your proposal response. In the answers of these questions the City of Dayton shall be noted as “City”.

To ensure the integrity of the proposal process, a signed copy of this proposal addendum notice shall be included with your company’s response to this document.

(Print Name)

(Date)

(Signature)

(Company Name)

Sincerely,

Eric Myers

Eric Myers, Administrator
Division of Water Reclamation
Department of Water

City of Dayton, Ohio
Department of Water
Division of Water Reclamation

WASTE/RECYCLING DISPOSAL & TRANSPORTATION SERVICES

Open Market

REQUEST FOR PROPOSAL (RFP) No. 21-012WTWT

March 2021

1. What is the condition of the boxes at Broadway Pump Station?

Answer: Broadway Station 1: The container is showing signs of corrosion at the bottom of the container and may need replaced in the next 12 months. Broadway Station 2: The container is in good condition. Do not anticipate it needing replaced in the next 12 months.

2. Is the tarping system on the 20-yard dumpsters at the back of the facility working?

Answer: The tarps are functional, and we have not encountered any major issues. Occasionally, the truck drivers will catch the tarping system in the rear door of the 20-yard container. When this occurs, it causes damage to the tarping system not allowing proper operation. The vendor's proposal should include options preventing the tarping system from getting caught in the rear door of the container. The vendor proposal should include the time it will take to resolve a damaged tarping system. The City's preference is not to use the hard-top covers. These were tried and did not work well.